HABS 1D, 30-5AL,V, 1-X-

HISTORIC AMERICAN BUILDINGS SURVEY

Index to Photographs

Leesburg Townsite, Ditches Napias Creek Salmon Vicinity Lemhi County Idaho HABS No. ID-106-X

NOTE: Photographs were taken Lon Johnson, photographer, June 1992 (ID-106-X-1 through ID-106-X-3) and September 1992 (ID-106-X-4 and ID-106-X-5)

ID-106-X-1	VIEW OF MINING DITCH HEADGATE STRUCTURES, SOUTH OF TOWNSITE, LOOKING NORTHWEST
ID-106-X-2	VIEW OF MINING DITCH, NORTH OF TOWNSITE, LOOKING NORTHWEST
ID-106-X-3	VIEW OF MINING DITCH, NORTH OF TOWNSITE, SHOWING HOUSE (Feature 1) [see ID-106-A] IN BACKGROUND, LOOKING SOUTH
ID-106-X-4	VIEW OF MINING DITCH, SOUTH OF TOWNSITE, LOOKING EAST
ID-106-Y-5	VIEW OF MINING DITCH SOUTH OF TOWNSITE LOOKING NORTH